

Why Should I Wear a

GVS P3 Mask?

DUST & FUME ARE DANGEROUS

BREATHING MIST FUMES & FOG CAN LEAD TO PNEUMONIA, CANCER, ASTHMA, SILICOSIS

High Efficiency Synthetic Particulate Airfilter Protects against



Dust

Dust forms when a solid material is broken down into tiny fragments. The finer the dust, the higher the risk.



Mist

Mists are tiny droplets that are formed from liquid materials by atomisation and condensation processes, such as spray painting.




Fumes

Fumes are formed when a solid material is vaporised by the high heat. The vapour cools quickly and condenses into very fine particles.



Welding, Cutting and Grinding metal



Costruction dust (silicia, concrete, cement, wood...)

FILTER TECHNOLOGY



1

Pull both elastics to wear the mask



2

Adjust the 4 points of the elastic straps



3

Cover the valve to check the mask is fitted


Filter must be changed when breathing becomes hard

Step below:



1

Turn the buckle inside clockwise



2

Open the grill



3

Remove the filter



4

Replace and close